

Residential Inspection Report

Inspection Date:

Tuesday, August 1, 2023

Prepared For:

Anywhere Florida

Prepared By:

Gem of The Hills Home Solutions, LLC Clermont, FL 34711

Phone: 352-459-5789

Email:

gemofthehillshomesolutions@gmail.com

Report Number:

Sample report

Inspector:

Jerry Pyle



This report is the exclusive property of Gem of The Hills Home Solutions, LLC and the client(s) whose name appears herewith, and its use by any unauthorized persons is prohibited.

Table of Contents

Report Overview	
Report Overview	6
Recommendations / Summary	7
1. Structure	
Description	10
Limitations	10
Foundation, Basement and Crawlspace	10
Columns or Piers	10
Walls	11
Floors	11
Ceilings	11
Roof Structure and Attic	11
2. Exterior	
Description	12
Limitations	12
Wall Clading	13
Trim & Flashing	14
Exterior doors	14
Windows (as seen from exterior)	14
Porches, Decks, Balconies, Steps and Railing	14
Driveways	14
<u>Vegitation</u>	14
Eaves, Soffits and Fascia	15
Additonal Buildings on Property	15
rrigation	15
3. Roofing	
Description	16
<u>_imitations</u>	17
Flashings	17
Skylights and Roof Penitrations	17
Roof Decking	17
Roof Drainage Systems	17

	Page 3 of 48
4. Insulation / Ventilation	
<u>Description</u>	18
<u>Limitations</u>	18
Insulation in Attic	19
Ventilation of Attic	19
Venting Systems	19
5. Electrical	
Description	20
Limitations	22
Service Entrance	22
Grounding	22
Service Disconnect Panel	22
Distribution Panel	23
Fixtures	23
Receptacles and Switches	23
GFCI (Ground FaultCircuit Interrupters)	23
Smoke/Carbon Monoxide Detectors	23
6. HVAC (HEATING & COOLING)	
<u>Description</u>	24
Limitations	25
Heating Equipment	25
Cooling Equipment	26
Thermostat	27
Air Filter	27
Distribution System (Ducts)	27
Appliance Venting	27
7. Plumbing	
Description	28
Limitations	29
Plumbing Drain and Waiste System	30
Water Supply and Distribution system	30
Hot Water System	30
Main Shut Off	30
8. Garage	

Description	, Page 4 of 48 31
Limitations	31
	31
Walls	
Floor	32
Ceiling	32
Fire Rated Door	32
Garage Door	32
Garage Door Opener and Sensors	32
9. Interior Rooms	
Description	33
Limitations	33
Flooring	34
Ceiling	34
Walls	34
Interior Doors	34
Steps and Stairways	34
Windows	34
Cabinetry	34
Moulding and Trim	34
11. Kitchen / Appliances	
Description	35
Limitations	37
Stove/Cooktop	37
Vent Hood	37
Microwave	37
Disposal	37
Dishwasher	38
Refrigerator	38
Cabinetry	38
Counter Tops	38
Sink and Faucet	38
12. Bathroom(s)	
Description	39
Limitations	39

	, Page 5 of 48
Vanity(s)	39
Shower/Tub/Enclosure	39
Water Closet/ Toilet	40
Vanity Tops	40
Sinks and Faucets	40
Lighting	40
Ventilation	40
13. Pool	
Description	41
Limitations	41
Pool Electrical	41
Pool Pump	41
Clorinator	43
Valves	43
Filter and housing	43
Heater	43
Pool Wall and Surface	43
Pool and spa lights	44
Frame Enclosure	44
Screening	44
Decking	44
Child & Pet protective fencing	45
Solar Panels	45
14. Thermal Imaging	
Description	46
Maintenance Advice	
Maintenance Advice	47

Report Overview

CONVENTIONS USED IN THIS REPORT

For your convenience, the following conventions and color codes have been used in this summary section.

Major Concern: a system or component which is considered significantly deficient or damaged. Significant deficiencies should to be corrected by qualified tradesman/specialist and are likely to involve significant expense.

Safety Issue: denotes a condition that is unsafe and in need of prompt attention. May or may not be a significant expense.

Deferred Cost Item: denotes a system or component that is old and is near, at, or beyond its normal life expectancy and shows indication that it may require replacement soon and is likely to involve a significant expense.

Repair: denotes a system or component which may be damaged, missing, or inoperative and which needs corrective action to assure proper and reliable function.

Improve: denotes typical homeowner type improvements which are recommended but could be deferred.

Specialist Needed: further evaluation by a licensed specialist in the building trades is needed (*preferably prior* to end of the inspection contingency period in the sales contract).

Please note that those observations listed under "Discretionary Improvements" are not essential repairs, but represent logical long term improvements. Multiple conventions are listed in cases where repairs may overlap one or more of the above conventions. Repair cost estimates are rough estimates only.

• For the purpose of this report, it is assumed that the house faces North. The home was furnished at the time of inspection (i.e. some areas not totally accessible for inspection).

IMPROVEMENT RECOMMENDATION HIGHLIGHTS / SUMMARY

The following is a synopsis of the potentially significant defects that should be budgeted for over the short term (*highlighted in color*). Other significant improvements, outside the scope of this inspection, may also be necessary. Please refer to the main body of this report for further details on these and other recommendations. Note: any repair cost estimates shown are order of magnitude estimates only. They pertain to <u>some</u> of the more significant observations (i.e. major concerns, safety issues, and deferred cost items) listed in this report. This is not an all-inclusive list of future repair costs, nor does it address general annual maintenance (*refer to end of report for helpful tips*). It is further recommended that qualified, licensed contractors/trades specialists be consulted for specific quotations or for any listed further evaluations. You may find that some contractor estimates vary dramatically from these figures, and from each other. Contractors may uncover 'hidden' defects not apparent at the time of the inspection, resulting in these additional costs.

MAJOR CONCERN'S

FOUNDATION, BASEMENT AND CRAWLSPACE

* Foundation is becoming exposed due to the wash away of ground near home. This is being caused by the lack of gutters. Recommend gutters be attached to home to help prevent further washout.

WALL CLADING

- * Stucco cracks are present throughout exterior. Stucco cracks are a result of typical shrinkage and setting and are not considered a structural defect. However, all stucco cracks require sealing to prevent water intrusions. Water intrusions will exasperate conditions and cause additional failures and damage in the future.
- * Exterior paint appears to beyond its serviceable life expectancy. Recommend repainting as soon as possible.
- * Exterior paint appears to beyond its serviceable life expectancy. Recommend repainting as soon as possible.

VEGITATION

* Palm tree in front yard is dead and in need of removal.

WATER CLOSET/ TOILET

* Water closet (toilet) is loose to floor inmaster bathroom. Mold or further damage may be present in areas that are not visible to inspector. Requires further evaluation and repair by a licensed contractor.

SAFETY ISSUES

MINOR CONCERN'S

WALL CLADING

* Stucco cracks are present throughout exterior. Stucco cracks are a result of typical shrinkage and setting and are not considered a structural defect. However, all stucco cracks require sealing to prevent water intrusions. Water intrusions will exasperate conditions and cause additional failures and damage in the future.

FIXTURES

* Although still operational ceiling fans on rear patio are corroded and in need of repair.

COOLING EQUIPMENT

* Overflow valve for a/c is full of water. Clogged overflow pipe is in need of cleaning by a certified HVAC technician.

REPAIR ITEMS

IMPROVEMENT ITEMS

THE SCOPE OF THE INSPECTION

All components designated for inspection in the InterNACHI Standards of Practice are inspected, except as may be noted in the "Limitations of Inspection" sections within this report. The goal is to identify major defects or adverse conditions that could result in injury or lead to costs that would significantly affect the evaluation of the property, and/or to alert you to the need for a specialist evaluation. We evaluate conditions, systems, and components, and report on their current condition, which does not mean that they are ideal but that they are either functional or met a reasonable standard at some point in time. We do take into consideration when a structure (e.g. house, condominium, garage, etc.) was built and allow for the predictable deterioration that would occur through time, such as the cracks that appear in concrete and in the plaster or drywall around windows and doors, scuffed walls or woodwork, worn or squeaky floors, and sticking (i.e. difficult to open, painted shut, etc.) windows. Therefore, we tend to ignore insignificant and predictable defects, and do not annotate them, and particularly those that would be apparent to the average person or to someone without any construction experience. We are not authorized, or have the expertise, to comment on termites or other wood damaging insects, dry rot, fungus, or mold/mildew, but may alert you to its presence (you should refer to your WDO inspection report, if applicable). Not all improvements will be identified during this inspection. Unexpected repairs should still be anticipated. The inspection should not be considered a guarantee or warranty of any kind (Note: defective items noted within this report may not be covered by a third party home warranty). This inspection does not include checking for compliance with building codes (unless it is a safety concern). The older a building is, the more likely that it does not meet today's building codes. If you want a 'code inspection' you'll need to talk to the local building department since they're the only people with the authority to do a code compliance inspection. If you find codes, specifications or standards referenced in this report you should realize that they're only provided as a reference source for opinions; they are not intended to imply that this code was in place at the time of construction, nor that this is a code compliance inspection. Not all code related issues can or will be disclosed in this report. We offer no warranty as to code compliance. Please refer to the Inspection Agreement contract and the Standards of Practice for a more complete explanation of the scope of the inspection.

In Attendance	Structure Type	Age of building
Nobody	Residential	15-20 years
Temperature	Weather	Ground conditions
Above 85 degrees	Sunny and dry	Normal

1. 1. Structure

DESCRIPTION OF 1. STRUCTURE

Foundation: Slab
Floor Structure: Slab
Wall Structure: Masonry
Ceiling Structure: Truss
Roof Structure: Trusses
Roof Type Gable

1.1 LIMITATIONS

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Structural components concealed behind finished surfaces (e.g. drywall, paneling, etc.) cannot be inspected.
- Crawlspaces that are not accessible or have limited access (<2 ft. of headroom) or that may contain hazardous materials or other potentially hazardous conditions to the inspector are not entered.
- Attic load bearing components (e.g. trusses, ceiling joists, etc.) covered with insulation cannot be traversed (i.e. walked upon). Thus, attics are typically inspected only at the access points (i.e. scuttle openings).
- Furniture and/or stored items may restrict access and the inspection to some areas in and around the home (e.g. home furnishings).
- Engineering or architectural services such as calculation of structural capacities, adequacy, or integrity are not part of a professional home inspection.

Please also refer the <u>Inspection Agreement</u> contract for a detailed explanation of the scope of this inspection.

1.2 FOUNDATION, BASEMENT AND CRAWLSPACE

Comments: INSPECTED-defective





Foundation is becoming exposed due to the wash away of ground near home. This is being caused by the lack of gutters. Recommend gutters be attached to home to help prevent further washout.

1.3 COLUMNS OR PIERS

Comments: Not Present

1.4 **WALLS**

Comments: INSPECTED

1.5 FLOORS

Comments: INSPECTED

1.6 CEILINGS

Comments: INSPECTED

1.7 ROOF STRUCTURE AND ATTIC

Comments: INSPECTED

Note: It is not plausible for an inspector to be able to inspect 100% of an attic space and its structure. As a minimum, areas within three feet of the fascia are not accessible. Due to conditions limiting the inspectors access or safety the inspector as an estimate was able to inspect 80-100%.

2. 2. Exterior

DESCRIPTION OF 2. EXTERIOR

Wall Covering:

Eaves, Soffits, and Fascias:

Exterior Doors:

Window/Door Frames and Trim:

Entry Driveways:

Entry Walkways and Patios:

Stucco

Aluminum

Metal

Aluminum

Pavers

Pavers

Porches, Decks, Steps, Railings: Concrete covered or enclosed

Overhead Garage Door(s): Steel

Surface Drainage: Graded Away From House

Retaining Walls: None Fencing: None

Exterior of Home







Exterior Right



Exterior Rear



Exterior Left

2.1 LIMITATIONS

This is a visual inspection limited in scope by (but not restricted to) the following conditions:

- A representative sample of exterior components was inspected rather than every occurrence of components.
- The inspection does not include an assessment of geological, geotechnical, or hydrological conditions, or environmental hazards.
- Screening, shutters, awnings, or similar seasonal accessories, fences, recreational facilities, outbuildings, seawall's, break walls, docks, erosion control and earth stabilization measures are not inspected unless specifically agreed-upon and documented in this report.

2.2 WALL CLADING

Comments: INSPECTED-defective





Stucco cracks are present throughout exterior. Stucco cracks are a result of typical shrinkage and setting and are not considered a structural defect. However, all stucco cracks require sealing to prevent water intrusions. Water intrusions will exasperate conditions and cause additional failures and damage in the future.



Exterior paint appears to beyond its serviceable life expectancy. Recommend repainting as soon as possible.

2.3 TRIM & FLASHING

Comments: INSPECTED

2.4 EXTERIOR DOORS

Comments: INSPECTED

2.5 WINDOWS (AS SEEN FROM EXTERIOR)

Comments: INSPECTED

2.6 PORCHES, DECKS, BALCONIES, STEPS AND RAILING

Comments: INSPECTED

2.7 DRIVEWAYS

Comments: INSPECTED

2.8 **VEGITATION**

Comments: INSPECTED-defective



Palm tree in front yard is dead and in need of removal.

2.9 EAVES, SOFFITS AND FASCIA

Comments: INSPECTED

2.10 ADDITONAL BUILDINGS ON PROPERTY

Comments: Not Present

2.11 IRRIGATION

Comments: INSPECTED-operational





Zone 1 Zone 2





Zone 3 Zone 4

3. 3. Roofing

DESCRIPTION OF 3. ROOFING

Roof Covering:Ceramic TileRoof Flashing's:MetalChimneys:NoneRoof Drainage System:NoneSkylights:None

Method of Inspection: From ladder (Material may be damaged if walked)

Roofing Pictures







3.1 LIMITATIONS

This is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Not all of the underside of the roof sheathing is inspected for evidence of leaks.
- Evidence of prior leaks may be disguised by interior finishes.
- Estimates of remaining roof life are approximations only and do not preclude the possibility of leakage. Leakage can develop at any time and may depend on rain intensity, wind direction, ice build up, and other factors.
- Antennae, chimney/flue interiors which are not readily accessible are not inspected and could require repair.
- * Roof inspection may be limited by access, condition, weather, or other safety concerns.

3.2 FLASHINGS

Comments: INSPECTED-Limited

Due to the shape and orientation of the roof Inspector could not visually inspect all flashing.

3.3 SKYLIGHTS AND ROOF PENITRATIONS

Comments: INSPECTED

3.4 ROOF DECKING

Comments: INSPECTED

3.5 ROOF DRAINAGE SYSTEMS

Comments: INSPECTED

4. 4. Insulation / Ventilation

DESCRIPTION OF 4. INSULATION / VENTILATION

Attic Insulation: Blown Fiberglass

Crawl Space Insulation: Other Vapor Retarders: Other

Roof Ventilation:Gable Vents • Roof Vents
Crawl Space Ventilation:
No Ventilation Found

Picture of Insulation in Attic



4.1 LIMITATIONS

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- The inspection does not include the presence, extent, and type of insulation and vapor barriers in the
 exterior walls which are typically not readily visible. If you wish to know more about the 'tightness' or
 energy efficiency of the home you should have a specialist further evaluate the home (e.g. energy
 rater).
- Insulation/ventilation type and levels in concealed areas cannot be determined (e.g. vaulted ceilings, covered walls, etc.). Furthermore, insulation and vapor barriers are not disturbed (i.e. not walked on or moved) and no intrusive or destructive tests (such as cutting openings in walls to look for insulation) are performed.
- Potentially hazardous materials such as <u>Asbestos, Vermiculite</u>, and Urea Formaldehyde Foam Insulation (<u>UFFI</u>) will be brought to your attention if present but these materials cannot be positively identified without a more detailed inspection and laboratory analysis. This is beyond the scope of the

inspection.

 Any estimates of insulation R values or depths are rough average values; insulation types and depths typically vary in attic spaces.

Please also refer to the <u>Inspection Agreement</u> contract for a detailed explanation of the scope of this inspection.

4.2 INSULATION IN ATTIC

Comments: INSPECTED

Insulation on horizontal areas





4.3 VENTILATION OF ATTIC

Comments: INSPECTED

4.4 VENTING SYSTEMS

Comments: INSPECTED

5. 5. Electrical

DESCRIPTION OF 5. ELECTRICAL

Size of Electrical Service:150 AmpService Drop:UndergroundService Entrance Conductors:Aluminum

Service Equipment &

Main Disconnects:OtherService Grounding:CopperSub-Panel(s):None visibleDistribution Wiring:Copper

Wiring Method: Non-Metalic Cable 'Romex'

Switches & Receptacles: Grounded

Ground Fault Circuit Interrupters: Bathroom(s) • Exterior • Garage • Kitchen

Smoke Detectors: Present

Service Disconnect







Disconnect without Cover








Distribution Wiring





Distribution Panel W/Cover

Distribution Panel W/O Cover

5.1 **LIMITATIONS**

This is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Electrical components concealed behind finished surfaces are not inspected.
- Only a representative sampling of outlets and light fixtures were tested.
- Furniture and/or storage restricted access to some electrical components which may not be inspected.
- ❖ The inspection does not include remote control devices, alarm systems and components, low voltage wiring, systems, and components, ancillary wiring, systems, and other components which are not part of the primary electrical power distribution system.

5.2 SERVICE ENTRANCE

Comments: INSPECTED

5.3 GROUNDING

Comments: INSPECTED

5.4 SERVICE DISCONNECT PANEL

Comments: INSPECTED

5.5 DISTRIBUTION PANEL

Comments: INSPECTED

5.6 FIXTURES

Comments: INSPECTED-defective





Although still operational ceiling fans on rear patio are corroded and in need of repair.

5.7 RECEPTACLES AND SWITCHES

Comments: INSPECTED

5.8 GFCI (GROUND FAULTCIRCUIT INTERRUPTERS)

Comments: INSPECTED

5.9 SMOKE/CARBON MONOXIDE DETECTORS

Comments: INSPECTED

Note: Smoke detectors/carbon monoxide detectors are not tested for function. All detectors should be replaced if older than five years of age.

6. 6. HVAC (HEATING & COOLING)

DESCRIPTION OF 6. HVAC (HEATING & COOLING)

Heating Energy Source: Gas

Heating System Type: Forced Air Furnace

Cooling Energy Source:ElectricityCooling System Type:Central AirHeat Distribution Methods:DuctworkOther Components:None

HVAC System One



Mfg Date of Compressor 2005



Overall Pic of Compressor



Mfg Date of Air Handler 2005



Overall Pic of Air Handler

Note: The typical life expectancy of the average system is 12-16 years. However, many homeowners will replace their systems after 10 years to achieve a higher efficiency rating. If you system is over 12 years it should be considered at the end of its life expectancy and replaced.

6.1 LIMITATIONS

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- We do not activate or operate heating and/or cooling systems that do not respond to normal controls (i.e. thermostat) or has been shut down.
- The efficiency of the heating supply or distribution balance is not determined (this is beyond the scope
 of the inspection).
- The interior condition of exhaust pipes and/or flues cannot be inspected without dismantling and thus is beyond the scope of the inspection.
- Furnace heat exchangers and/or evaporative coils within forced air HVAC systems are not inspected (this would generally require dismantling of the equipment which is beyond the scope and should only be performed by a licensed HVAC technician).
- Solar space heating equipment/systems are not inspected. You should have them inspected by a specialist.
- Heating equipment controls and/or gauges are not dismantled for any reason.
- A check of the system pressure, current draws and/or any other technical HVAC (Heating/Ventilation/Air Conditioning) system checks are beyond the scope of the inspection.
- Window mounted air conditioning units are not inspected since these are considered portable units.
- Air conditioning systems are not activated when outside air temperature is below 50 degrees F (*or has been in the last 24 hrs*) to prevent damage to the equipment.
- Potentially hazardous materials such as <u>Asbestos</u>, wrapping over ductwork cannot be positively
 identified without a more detailed inspection and laboratory analysis. This is beyond the scope of the
 inspection. However, we will alert you to the presence of the material (typically found in older homes).

Please also refer to the Inspection Agreement contract for a detailed explanation of the scope of this inspection.

6.2 HEATING EQUIPMENT

Comments: INSPECTED-operational

Heating System One Temperature







Return Air temperature



Picture of Coils

6.3 COOLING EQUIPMENT

Comments: INSPECTED-operational

Cooling System One Temperature



Cool Supply Temperature



Return Air temperature



Overflow valve for a/c is full of water. Clogged overflow pipe is in need of cleaning by a certified HVAC

technician.

6.4 THERMOSTAT

Comments: INSPECTED-operational

6.5 AIR FILTER

Comments: INSPECTED

6.6 DISTRIBUTION SYSTEM (DUCTS)

Comments: INSPECTED

Ductwork



6.7 APPLIANCE VENTING

Comments: INSPECTED

7. 7. Plumbing

DESCRIPTION OF 7. PLUMBING

Water Supply Source: Public Water Supply

Service Pipe to House: PVC/CPVC
Main Water Valve Location: Exterior Right

Interior Supply Piping: CPVC

Waste System: Public Sewer

Drain, Waste, & Vent Piping: PVC Water Heater: Gas



Overall of Water Heater







Manufacture Date

Pressure Relief Valve





Drain Pipes in Residence

Distribution Pipes





Washer Drain

Main Shut Off





Back Flow Preventer

Water temperature

7.1 LIMITATIONS

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Winterized' plumbing systems cannot be operated and tested for leaks (this includes both water supply and drain lines). We recommend the home (or building) be 'de-winterized' prior to inspection.
- Activation or operation of a water heater that does not respond to normal controls (i.e. thermostat) or has been shut down.
- Portions of the plumbing system concealed by finishes and/or stored items (e.g. below sinks, behind walls, etc.), below the structure, or beneath the ground surface are not inspected.
- Water quality is not determined in this report (refer to the well and septic evaluation report, if applicable).
- Water conditioning systems (e.g. softeners, iron extractors, filtrations systems, etc.), solar water heaters, fire and lawn sprinkler systems are not inspected.
- The location of private wells and waste disposal systems are not verified and are not inspected (Note: Sellers are usually responsible for this).
- Pools (above or below ground) and/or hot tub inspections are outside the scope of this inspection. We recommend you have a specialist evaluate them.
- Overflow drains (e.g. basement floor drains) are not tested.
- Hose bibs are not tested during the winter months or when outside temperatures are below freezing.

Please also refer to the Inspection Agreement contract for a detailed explanation of the scope of this inspection.

7.2 PLUMBING DRAIN AND WAISTE SYSTEM

Comments: INSPECTED

7.3 WATER SUPPLY AND DISTRIBUTION SYSTEM

Comments: INSPECTED

7.4 HOT WATER SYSTEM

Comments: INSPECTED

7.5 MAIN SHUT OFF

Comments: INSPECTED

8. **8.** Garage

DESCRIPTION OF 8. GARAGE

Garage Type: Integrated Garage

Garage Doors: One Garage Door Material(s): Steel

Overall of Garage Interior



8.1 **LIMITATIONS**

As prescribed in the pre-inspection contract, this is a visual inspection only. The inspection was limited by (but not restricted to) the following conditions:

- Components concealed behind finished surfaces (e.g. framing) cannot be inspected.
- Stored items and/or automobiles within the garage may limit the inspection.
- Ancillary outbuildings and/or structures (e.g. pole barns, sheds, playground equipment, seawalls, etc.) are not inspected (unless specifically requested by contract Note: additional fees apply).

Please also refer to the <u>Inspection Agreement</u> contract for a detailed explanation of the scope of this inspection.

8.2 WALLS

Comments: INSPECTED

8.3 FLOOR

Comments: INSPECTED-Limited

Garage floor could not be inspected properly due to stored materials.

8.4 CEILING

Comments: INSPECTED





8.5 FIRE RATED DOOR

Comments: INSPECTED

8.6 GARAGE DOOR

Comments: INSPECTED-operational

8.7 GARAGE DOOR OPENER AND SENSORS

Comments: INSPECTED-operational

9. 9. Interior Rooms

DESCRIPTION OF 9. INTERIOR ROOMS

Wall and Ceiling Materials:

Floor Surfaces:

Window Type(s) & Glazing:

Dorywall

Laminate • Tile

Single Pane

Wood-Hollow Core

Bedroom Count: 3
Bathroom Count: 2

Interior of Home



9.1 LIMITATIONS

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions

- Home furnishing, personal stored items, appliances and/or wall hangings are not moved (*in most cases*) to permit inspection and may block defects. We recommend re-inspection of the property for all occupied homes upon vacancy or at 'final walk-thru' (*Note: additional fees may apply*).
- Window treatments, wallpaper, and other interior finish treatments are not the focus of this inspection (considered as cosmetic) and therefore not inspected.
- Attached wall coverings, ceiling coverings, and/or panels are not removed which may destroy the items being
 evaluated.
- The cosmetic condition of floors, walls, and ceiling coverings are not focused on in this report, but may be brought to your attention.
- Recreational facilities, alarms, intercoms, speaker systems, radio controlled devices, security devices are not inspected.
- An analysis of indoor air quality is not part of the inspection unless explicitly contracted-for and discussed in
 this or a separate report. Also excluded are the determination/testing of molds, mildew, insects, and other
 flora or fauna and their consequent damage, toxicity, odors, waste products, and noxiousness (although we

Please also refer to the <u>Inspection Agreement</u> contract for a detailed explanation of the scope of this inspection.

0.2 FLOORING	
Comments: INSPECTED	
0.3 CEILING	
Comments: INSPECTED	
0.4 <u>WALLS</u>	
Comments: INSPECTED	
0.5 INTERIOR DOORS	
3.3 INTERIOR DOORS	_
Comments: INSPECTED	
0.6 STEPS AND STAIRWAYS	
Comments: INSPECTED	
0.7 WINDOWS	
Comments: INSPECTED	
0.8 CABINETRY	
Comments: INSPECTED	
9.9 MOULDING AND TRIM	
Comments: INSPECTED	

10. 11. Kitchen / Appliances

DESCRIPTION OF 11. KITCHEN / APPLIANCES

Wall and Ceiling Materials:

Floor Surfaces:

Kitchen Cabinets:

Countertop(s):

Drywall

Wood

Granite


Appliances Tested: Electric Range • Microwave Oven • Dishwasher • Waste Disposer • Refrigerator

• Clothes Dryer • Clothes Washer

Dryer: Electric

Kitchen Overall





This confidential report is prepared exclusively for Anywhere Florida © Gem of The Hills Home Solutions, LLC



Microwave

10.1 LIMITATIONS

As prescribed in the pre-inspection contract, this is a visual inspection only. The inspection was limited by (but not restricted to) the following conditions:

- Components concealed behind finished surfaces could not be inspected.
- Programmable thermostats, timers and other specialized features and controls are not tested.
- The temperature calibration, functionality of timers, effectiveness, efficiency and overall performance of appliances is outside the scope of this inspection.
- Stored items within cabinetry may hide additional defects (i.e. and may be labeled as not visible for inspection).
- Small household appliances or other <u>non-built-in appliances</u> are not inspected (e.g. portable dishwashers, non-built-in stoves, countertop microwaves, etc.).
- Laundry machines are not tested as these are considered 'portable' appliances. Central vacuum systems are not inspected.
- Timers and other specialized appliance features and/or controls are not inspected.
- The temperature calibration, functionality of timers, effectiveness, efficiency and overall performance of appliances is outside the scope of this inspection.
- Information from manufacturer recalls or information contained in the <u>Consumer Protection</u> Bulletin is excluded from this report.

Please also refer to the <u>Inspection Agreement</u> contract for a detailed explanation of the scope of this inspection.

10.2 STOVE/COOKTOP

Comments: INSPECTED-operational

10.3 VENT HOOD

Comments: INSPECTED-operational

10.4 MICROWAVE

Comments: INSPECTED-operational

10.5 DISPOSAL

Comments: INSPECTED-operational

1	0.0	6 D	IS	Н٧	V۸	SI	HER
---	-----	-----	----	----	----	----	------------

Comments: INSPECTED-operational

10.7 REFRIGERATOR

Comments: INSPECTED-operational

10.8 CABINETRY

Comments: INSPECTED

10.9 COUNTER TOPS

Comments: INSPECTED

10.10 SINK AND FAUCET

11. 12. Bathroom(s)

DESCRIPTION OF 12. BATHROOM(S)

Wall and Ceiling Materials: Drywall Floor Surfaces: Tile

Bathroom Overall



11.1 LIMITATIONS

As prescribed in the pre-inspection contract, this is a visual inspection only. The inspection was limited by (but not restricted to) the following conditions:

- Components concealed behind finished surfaces cannot be inspected.
- Steam rooms and/or saunas are not inspected (beyond the scope).
- Outhouses are not inspected.

Please also refer to the <u>Inspection Agreement</u> contract for a detailed explanation of the scope of this inspection.

11.2 **VANITY(S)**

Comments: INSPECTED

11.3 SHOWER/TUB/ENCLOSURE

Comments: INSPECTED-defective



Water closet (toilet) is loose to floor inmaster bathroom. Mold or further damage may be present in areas that are not visible to inspector. Requires further evaluation and repair by a licensed contractor.

11.5 VANITY TOPS

Comments: INSPECTED

11.6 SINKS AND FAUCETS

Comments: INSPECTED

11.7 LIGHTING

Comments: INSPECTED

11.8 VENTILATION

DESCRIPTION OF 13. POOL

Filter Type: Pleated Cartridge
Heater Type: Natural Gas
Enclosure Present: Yes

Overall picture of equipment



12.1 LIMITATIONS	
12.2 POOL ELECTRICAL	
12.3 POOL PUMP	















12.5 **VALVES**

12.6 FILTER AND HOUSING

12.7_HEATER

Comments: INSPECTED-operational



12.8 POOL WALL AND SURFACE







12.9 POOL AND SPA LIGHTS

12.10 FRAME ENCLOSURE

Comments: INSPECTED









12.11 SCREENING

Comments: INSPECTED

12.12 **DECKING**





12.13 CHILD & PET PROTECTIVE FENCING

12.14 SOLAR PANELS

Comments: Not Present

13. 14. Thermal Imaging

DESCRIPTION OF 14. THERMAL IMAGING

Thermal info...

Logo

Maintenance Advice

UPON TAKING OWNERSHIP

	fter taking possession of a new home, there are some maintenance and safety issues that should be addressed nmediately. The following checklist should help you undertake these improvements:
	1 Change the locks on all exterior entrances, for improved security.
	1 Check that all windows and doors are secure. Improve window hardware as necessary. Security rods can be added to sliding windows and doors. Consideration could also be given to a security system.
	Install smoke detectors on each level of the home. Ensure that there is a smoke detector outside all sleeping areas.
_	
	Create a plan of action in the event of a fire in your home. Ensure that there is an operable window or door in every room of the house. Consult with your local fire department regarding fire safety issues and what to do in the event of fire.
	Examine driveways and walkways for trip hazards. Undertake repairs where necessary.
	Examine the interior of the home for trip hazards. Loose or torn carpeting and flooring should be repaired.
	Undertake improvements to all stairways, decks, porches and landings where there is a risk of falling or stumbling.
	Review your home inspection report for any items that require immediate improvement or further investigation Address these areas as required.
	Install rain caps and vermin screens on all chimney flues, as necessary.
	Investigate the location of the main shut-offs for the plumbing, heating and electrical systems. If you attended the home inspection, these items would have been pointed out to you.
REGUL	AR MAINTENANCE
E	VERY MONTH
	Check that fire extinguisher(s) are fully charged. Re-charge if necessary.
	Examine heating/cooling air filters and replace or clean as necessary.
	Inspect and clean humidifiers and electronic air cleaners.
	If the house has hot water heating, bleed radiator valves.
	Clean gutters and downspouts. Ensure that downspouts are secure, and that the discharge of the downspouts is appropriate. Remove debris from window wells.
	Carefully inspect the condition of shower enclosures. Repair or replace deteriorated grout and caulk. Ensure that water is not escaping the enclosure during showering. Check below all plumbing fixtures for evidence of leakage.
	Repair or replace leaking faucets or shower heads.
	Secure loose toilets, or repair flush mechanisms that become troublesome.
S	PRING AND FALL
_	

	, Page 48 of 48							
	Trim back tree branches and shrubs to ensure that they are not in contact with the house.							
	Inspect the exterior walls and foundation for evidence of damage, cracking or movement. Watch for bird nests or other vermin or insect activity.							
	Survey the basement and/or crawl space walls for evidence of moisture seepage. Look at overhead wires coming to the house. They should be secure and clear of trees or other obstructions.							
	Ensure that the grade of the land around the house encourages water to flow away from the foundation.							
	Inspect all driveways, walkways, decks, porches, and landscape components for evidence of deterioration, movement or safety hazards.							
	Clean windows and test their operation. Improve caulking and weather-stripping as necessary. Watch for evidence of rot in wood window frames. Paint and repair window sills and frames as necessary.							
	Test all ground fault circuit interrupter (GFCI) devices, as identified in the inspection report.							
	Shut off isolating valves for exterior hose bibs in the fall, if below freezing temperatures are anticipated.							
	Test the Temperature and Pressure Relief (TPR) Valve on water heaters.							
	Inspect for evidence of wood boring insect activity. Eliminate any wood/soil contact around the perimeter of the home.							
	Test the overhead garage door opener, to ensure that the auto-reverse mechanism is responding properly. Clean and lubricate hinges, rollers and tracks on overhead doors. Replace or clean exhaust hood filters.							
	Clean, inspect and/or service all appliances as per the manufacturer's recommendations.							
ΑN	NUALLY							
	Replace smoke detector batteries.							
	Have the heating, cooling and water heater systems cleaned and serviced.							
	Have chimneys inspected and cleaned. Ensure that rain caps and vermin screens are secure.							
	Examine the electrical panels, wiring and electrical components for evidence of overheating. Ensure that all components are secure. Flip the breakers on and off to ensure that they are not sticky.							
	If the house utilizes a well, check and service the pump and holding tank. Have the water quality tested. If the property has a septic system, have the tank inspected (and pumped as needed).							
	If your home is in an area prone to wood destroying insects (termites, carpenter ants, etc.), have the home inspected by a licensed specialist. Preventative treatments may be recommended in some cases.							

PREVENTION IS THE BEST APPROACH

Although we've heard it many times, nothing could be more true than the old cliché "an ounce of prevention is worth a pound of cure." Preventative maintenance is the best way to keep your house in great shape. It also reduces the risk of unexpected repairs and improves the odds of selling your house at fair market value, when the time comes.

Please feel free to contact our office should you have any questions regarding the operation or maintenance of your home. Enjoy your home!

Scan our contact info for future reference directly into your smart-phone here >